

## TABLE OF FIGURES

- Figure 1 Flight profile
- Figure 2 Position of the Pitot probes on the Airbus A330
- Figure 3 Pitot probe (with protection caps)
- Figure 4 Diagram of the speed measurement system architecture
- Figure 5 FCU display
- Figure 6 PFD in normal law
- Figure 7 PFD in alternate 2 law
- Figure 8 Pitot probe diagram
- Figure 9 Overview
- Figure 10 Effect of a drop in total measured pressure on standard altitude and vertical speed
- Figure 11 Evolution of stall warning threshold in relation to Mach
- Figure 12 Example of a "PROG" page from FMS
- Figure 13 TEMSI chart overlaid with infrarouge image at 0 h 00
- Figure 14 Strip filled out by ATLANTICO controller
- Figure 15 Representation of air traffic by the Eurocat system
- Figure 16 FDR
- Figure 17 CVR
- Figure 18 FDR CSMU after removal of cover
- Figure 19 FDR memory board
- Figure 20 Removal of internal protective layers
- Figure 21 Opening of CVR CSMU
- Figure 22 CVR memory board after removal of thermal protections
- Figure 23 CVR memory boards before cleaning
- Figure 24 Level of turbulence observed during flight
- Figure 25 Position and detail of "AIR DATA" selector
- Figure 26 Parameters from 2 h 10 min 04 to 2 h 10 min 26
- Figure 27 Parameters from 2 h 10 min 26 to 2 h 10 min 50
- Figure 28 Parameters from 2 h 10 min 50 to 2 h 11 min 46
- Figure 29 Optical disk showing the location of the readable zones
- Figure 30 Memory component from one of the FCDC
- Figure 31 All of floating debris (found between 6 and 26 June), last known position and wreckage site
- Figure 32 Wreckage localisation
- Figure 33 Position of the recovered parts (exterior and cargo)
- Figure 34 Position of the cabin part debris recovered in relation to the aircraft layout
- Figure 35 Part of Galley G3: downwards deformation at the level of the galley's heavy parts

- Figure 36** Luggage rack fitting deformed towards the front Toilet door (L54)
- Figure 37** Metallic stiffeners deformed by buckling
- Figure 38** Floor of the LDMCR: with bottom-upwards deformation
- Figure 39** Ceiling of the LDMCR: with top-downwards deformation
- Figure 40** Passenger oxygen container recovered closed: the deformations on the cover matched those on the box
- Figure 41** Passenger oxygen container recovered open: the three pins are in place
- Figure 42** Flap extension mechanism (or flap track) No. 3 in retracted position
- Figure 43** Part of the No. 3 flap track fairing on the left wing
- Figure 44** Fin – In the foreground the base of the fin with the central and forward attachment lugs
- Figure 45** Rib 2 bent upwards as a result of bottom-upwards compression loads
- Figure 46** HF antenna support
- Figure 47** Arm 36G, right view: failure of the rudder attachments
- Figure 48** Frame 87: shearing of the frame and fuselage skin along the frame
- Figure 49** Right-hand aft lug: shearing of the fuselage along main frames 86-87
- Figure 50** Frames 84 to 87: S-shaped deformation of frame 87, with frames 84 and 85 pushed in backwards; failure of the horizontal stabiliser actuator supports between frames 86 and 87 (red circle)
- Figure 51** Fin centre and aft attachments
- Figure 52** Rear view of the left-hand aft lug: there were marks showing a backwards pivoting of frames 86 and 87
- Figure 53** Tensile failure of the centre spar at the level of the attachment of the lateral load pick-up rods
- Figure 54** Compression failure of the aft spar at the level of the attachments of the lateral load pick-up rods and failure of the left-hand rod by buckling
- Figure 55** Sonar Images of the debris field
- Figure 56** Parts of the fuselage
- Figure 57** Left engine air intake
- Figure 58** Engine pylon
- Figure 59** Cartography of the parts subsequently brought to the surface
- Figure 60** Front view of engine
- Figure 61** Trimmable horizontal stabiliser screwjack after being raised on board
- Figure 62** Evolutions of recorded angles of attack and of the stall warning trigger threshold
- Figure 63** Comparison between the recorded positions of the elevator and THS and the simulation
- Figure 64** Comparison between altitudes of the aeroplane and the simulation (longitudinal axis)
- Figure 65** Flight envelope
- Figure 66** Evolution of normal acceleration recorded at the time of activation of the stall warning
- Figure 67** Speed displays on the PFD
- Figure 68** Evolution of the 3 CAS
- Figure 69** Evolution of FD crossbars
- Figure 70** Position of the area where ECAM messages are displayed

- Figure 71 ECAM displays at different moments (if no message has been erased)
- Figure 72 Evolution of the REC MAX (simulation) Source Airbus
- Figure 73 Source: Airbus FCOM supplied to Air France
- Figure 74 Source FCOM Airbus
- Figure 75 Source TU Air France
- Figure 76 View of the cockpit seats
- Figure 77 General view of the left seat
- Figure 78 The seat's horizontal position adjustment systems
- Figure 79 Right seat armrest on the side-stick side
- Figure 80 Roller marks on the guidance rail
- Figure 81 Right side seat cushion
- Figure 82 Marks on the adjustment mechanism
- Figure 83 Dial indicating armrest position
- Figure 84 Malformation of the crotch belt fastening
- Figure 85 A typical display on a flight logging interface
- Figure 86 Strip created after coordination between ATLANTICO and DAKAR Océanic
- Figure 87 Arrangement of the SRR in metropolitan France
- Figure 88 Lift graph with high and low Mach
- Figure 89 Flight envelope at high altitude
- Figure 90 Alucia
- Figure 91 AUV REMUS 6000
- Figure 92 General view using sonar imaging: 120 kHz, range of 700 m
- Figure 93 Engine
- Figure 94 Wing
- Figure 95 Section of fuselage
- Figure 96 Landing gear
- Figure 97 Overlay of sonar images taken with various settings: 120 kHz, 700 m range scale - 410 kHz, 100 m range scale - 410 kHz, 50 m range scale
- Figure 98 Visualisation of the photo mosaic obtained with REMUS AUV images and the aeroplane debris identified by using the REMORA ROV